

Errata Sheet for Advisory Circular (AC) 150/5320-6F, Airport Pavement Design and Evaluation

Last Update: 2/27/2017

This errata sheet logs content errors and required updates identified after the Advisory Circular was signed on November 10, 2016. These errors have been corrected in the consolidated PDF version of the AC available on the FAA website.

#	Description of Correction	Location in Document	Rationale	Date Error Corrected
1	Changes formula from E (psi) = $20.15 \times K1.284$ (k in pci) to E (psi) = $20.15 \times K^{1.284}$ (k in pci).	Par. 2.5.4	In the formula, 1.284 should have been shown as an exponent.	2/27/2017